

Disposal Facility Inspection Report (52) - Draft

Enforcement Agency:		County of Los Angeles			
SWIS Facility File Number (99-xx-9999)		Inspection Date		Program Code	
19-AA-0052		2/9/2011		LEA Periodic	
Time In		Time Out		Inspection Time	
Facility Name			Received By		
Chiquita Canyon Sanitary Landfill			Chiquita Canyon, Inc.		
Facility Location			Owner Name		
29201 Henry Mayo Drive, Castaic 91384					
Inspector			Also Present (Name)		
CASTELLANOS					

THE ABOVE FACILITY WAS INSPECTED FOR COMPLIANCE WITH APPLICABLE SECTIONS OF THE DIVISION 30 OF THE PUBLIC RESOURCES CODE (PRC) AND TITLE 14 AND TITLE 27 CALIFORNIA CODE OF REGULATIONS (CCR)

X	No Violations or Areas of Concern	
V	A	Regulations
Inspection Report Comments:		
<p>HOURS OF OPERATIONS FROM 4:30AM TO 5:00PM MONDAY. TUESDAY THROUGH FRIDAY 3:00AM TO 5:00PM. SATURDAYS FROM 4:30AM TO 2:00PM. PERMITTED TONNAGE IS 6000 TPD. DAILY PEAK TONNAGE 4,500 TPD. PERIMETER GAS PROBES 5,6,7 and 15. NO METHANE DETECTED AT THESE PROBES.</p> <p>THE FOLLOWING RECORDS WERE CHECKED AND FOUND SATISFACTORY: SAFETY MEETINGS,DAILY AND SPECIAL OCCURRANCES AND COMPLAINTS.</p> <p>LAST MONTH VIOLATION TO PRC 44014(b) HAS BEEN ABATED. A REVIEW OF THE TONNAGE REPORT INDICATE THAT INCOMING WASTE TONNAGE WAS KEPT UNDER THE 6,000 TPD.</p> <p>LAST MONTH AREA OF CONCERN 20790 HAS BEEN ABATED NO GAS LIKE ODORS DETECTED AT FLARE STATION.</p> <p>BIRD AND DUST CONTROL SATISFACTORY.</p> <p>WINDY CONDITIONS AT THE TIME OF INSPECTION, LITTER WAS OBSERVED ON SLOPES AND ON AREAS OUTSIDE THE DISPOSAL AREA. LANDFILL STAFF IS TAKING ALL NECESSARY MEASURES TO CONTROL LITTER INSIDE AND OUTSIDE DISPOSAL AREAS. LEA WILL MONITOR LITTER CONTROL IN THE FOLLOWING DAYS.</p> <p>NO LITTER OBSERVED ON HWY 126 AND STREET SWEEPER WAS IN OPERATION.</p> <p>LIGHTING DURING DARK WAS SATISFACTORY.</p> <p>A VALVERDE COMMUNITY SURVEY WAS CONDUCTED IN THE MORNING AND AFTERNOON AND NO ODORS WERE DETECTED.</p> <p>WASTE TO ENERGY PLANT IS IN OPERATION.</p> <p>NO SIGNIFICANT VIOLATIONS OBSERVED AT THE TIME OF INSPECTION</p>		